

## EAST Search History

| Ref # | Hits | Search Query   | DBs   | Default Operator | Plurals | Time Stamp       |
|-------|------|--|---|------------------|---------|------------------|
| S1    | 2    | "20040201096"  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:03 |
| S2    | 2289 | @ad<="20040330" and (257/678).<br>ccls.  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:13 |
| S3    | 2099 | @ad<="20040330" and<br>(257/697-698).ccls.   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:04 |
| S4    | 1585 | @ad<="20040330" and (257/700).<br>ccls.  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:04 |
| S5    | 1913 | @ad<="20040330" and (257/784).<br>ccls.  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:38 |
| S6    | 1756 | @ad<="20040330" and (257/786).<br>ccls.  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:07 |
| S7    | 10   | @ad<="20040330" and 'flexible'<br>same 'wiring circuit' and 'solder ball'<br>and 'printed circuit board'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:16 |
| S8    | 1    | "6580031".PN.  | USPAT;<br>USOCR   | OR               | ON      | 2005/10/20 09:10 |
| S9    | 1    | "6580031".PN.  | USPAT;<br>USOCR   | OR               | ON      | 2005/10/20 09:11 |
| S10   | 6144 | @ad<="20040330" and<br>(361/749-750).ccls. or (361/760).<br>ccls. or (361/792).ccls. or<br>(361/795).ccls. or (257/686).ccls. or<br>(257/685).ccls. or (257/688).ccls. | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:16 |
| S11   | 21   | @ad<="20040330" and 'flexible'<br>same 'wiring substrate' and 'solder<br>ball' and 'printed circuit board'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR               | ON      | 2005/10/20 09:20 |

## EAST Search History

|     |      |   |   |    |    |                  |
|-----|------|---|---|----|----|------------------|
| S12 | 864  | S10 and 'flexible' with 'substrate'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 09:17 |
| S13 | 235  | @ad<="20040330" and 'wiring<br>substrate' and 'solder ball' and<br>'printed circuit board'  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2006/02/23 11:38 |
| S14 | 1    | "6285081".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:30 |
| S15 | 1    | "6181569".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:30 |
| S16 | 1    | "6114187".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:31 |
| S17 | 1    | "6005292".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:31 |
| S18 | 1    | "5900738".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:33 |
| S19 | 1    | "5414371".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:33 |
| S20 | 1    | "5086337".PN.   | USPAT;<br>USOCR   | OR | ON | 2005/10/20 09:33 |
| S21 | 3938 | @ad<="20040330" and<br>(257/773-774).ccls.  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 09:38 |
| S22 | 931  | @ad<="20040330" and ('wiring<br>board' or 'wiring tape') and 'solder<br>ball' and ('printed circuit board' or<br>'PCB')                         | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 10:15 |
| S23 | 6    | @ad<="20040330" and ('wiring<br>board' or 'wiring tape') and 'solder<br>ball' and ('printed circuit board' or<br>'PCB') and 'metal stud'        | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 10:15 |
| S24 | 10   | @ad<="20040330" and ('wiring<br>board' or 'wiring tape') and 'solder<br>ball' and ('printed circuit board' or<br>'PCB') and 'metal' with 'stud' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 10:16 |
| S25 | 8    | @ad<="20040330" and ('wiring<br>board' or 'wiring tape') and 'solder<br>ball' and ('printed circuit board' or<br>'PCB') and 'metal' with 'plug' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 10:16 |

## EAST Search History

|     |     |  |   |    |     |                  |
|-----|-----|--|---|----|-----|------------------|
| S26 | 180 | @ad<="20040330" and ('wiring board' or 'wiring tape') and 'solder ball' and ('printed circuit board' or 'PCB') and 'metal' with 'bump' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 11:15 |
| S27 | 2   | ("6329610").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/10/20 10:56 |
| S28 | 9   | ((("5811982") or ("5914614") or ("6329827") or ("6722032"))).PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/10/20 11:08 |
| S29 | 1   | "5177438".PN.  | USPAT;<br>USOCR   | OR | ON  | 2005/10/20 10:58 |
| S30 | 1   | "5576630".PN.  | USPAT;<br>USOCR   | OR | ON  | 2005/10/20 10:58 |
| S31 | 4   | ((("6288905") or ("6376769"))).PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/10/20 11:08 |
| S32 | 951 | @ad<="20040330" and 'flexible' with 'substrate' and 'copper' and 'solder ball' and ('printed circuit board' or 'PCB')                  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 11:16 |
| S33 | 353 | @ad<="20040330" and 'flexible' with 'substrate' and 'copper' and 'solder ball' and 'PCB'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 11:16 |
| S34 | 51  | @ad<="20040330" and 'wiring substrate' and 'copper' and 'solder ball' and 'PCB'  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 11:25 |
| S35 | 233 | @ad<="20040330" and 'wiring board' and 'copper' and 'solder ball' and 'PCB'  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 11:17 |
| S36 | 4   | @ad<="20040330" and 'wiring tape' and 'copper' and 'solder ball' and 'PCB'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 11:17 |

## EAST Search History

|     |     |  |   |    |    |                  |
|-----|-----|--|---|----|----|------------------|
| S37 | 0   | @ad<="20040330" and 'fixibel' same 'substrate' and 'copper' with 'pillar' and 'solder ball' and 'PCB'  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:25 |
| S38 | 0   | @ad<="20040330" and 'fixibel' same 'substrate' and 'copper' and 'solder ball' and 'PCB'                | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:25 |
| S39 | 0   | @ad<="20040330" and 'flexible' same 'substrate' and 'copper' with 'pillar' and 'solder ball' and 'PCB' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:26 |
| S40 | 425 | @ad<="20040330" and 'flexible' same 'substrate' and 'copper' and 'solder ball' and 'PCB'               | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:28 |
| S41 | 6   | @ad<="20040330" and 'flexible' same 'substrate' and 'copper' same 'pillar' and 'solder ball' and 'PCB' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:26 |
| S42 | 105 | @ad<="20040330" and 'flexible' same 'substrate' and 'copper' same 'bump' and 'solder ball' and 'PCB'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:57 |
| S43 | 5   | @ad<="20040330" and 'flexible' same 'substrate' and 'copper' with 'stud' and 'solder ball' and 'PCB'   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 11:28 |
| S44 | 1   | "6010769".PN.  | USPAT;<br>USOCR   | OR | ON | 2005/10/20 11:36 |
| S45 | 1   | "5876842".PN.  | USPAT;<br>USOCR   | OR | ON | 2005/10/20 11:39 |
| S46 | 1   | "5744758".PN.  | USPAT;<br>USOCR   | OR | ON | 2005/10/20 11:39 |
| S47 | 1   | "5600103".PN.  | USPAT;<br>USOCR   | OR | ON | 2005/10/20 11:40 |
| S48 | 1   | "5510216".PN.  | USPAT;<br>USOCR   | OR | ON | 2005/10/20 11:40 |
| S49 | 67  | @ad<="20040330" and 'tape' same 'interposer' and 'copper' and 'solder ball' and 'PCB'                  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | ON | 2005/10/20 12:12 |

## EAST Search History

|     |      |   |   |    |     |                  |
|-----|------|---|---|----|-----|------------------|
| S50 | 2    | ("6081026").PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2005/10/20 12:06 |
| S51 | 1    | "5854534".PN.   | USPAT;<br>USOCR   | OR | ON  | 2005/10/20 12:09 |
| S52 | 96   | @ad<="20040330" and 'flexible'<br>same 'interposer' and 'copper' and<br>'solder ball' and 'PCB' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 12:12 |
| S53 | 80   | @ad<="20040330" and 'flexible'<br>with 'interposer' and 'copper' and<br>'solder ball' and 'PCB' | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2005/10/20 12:12 |
| S54 | 2    | @ad<="20040330" and "wiring<br>substrate" same "solder ball" same<br>"PCB"                      | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:39 |
| S55 | 1267 | @ad<="20040330" and "wiring<br>substrate" same ("solder ball" or<br>"bump")                     | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:39 |
| S56 | 13   | @ad<="20040330" and "wiring<br>substrate" same ("bump") same<br>"plug"                          | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:41 |
| S57 | 1032 | @ad<="20040330" and "wiring<br>substrate" same "bump"   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:41 |
| S59 | 1234 | @ad<="20040330" and "wiring<br>board" same "solder bump"  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:41 |
| S60 | 246  | @ad<="20040330" and "wiring<br>board" with "bump" same "copper"                                 | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:45 |
| S61 | 101  | @ad<="20040330" and "wiring<br>circuit board" with "bump"                                       | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:50 |

## EAST Search History

|     |    |  |   |    |     |                  |
|-----|----|--|---|----|-----|------------------|
| S62 | 2  | @ad<="20040330" and "wiring circuit board" and "plug" with "solder ball"   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:51 |
| S63 | 16 | @ad<="20040330" and "wiring circuit board" and "metal" with "solder ball"  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:51 |
| S64 | 30 | @ad<="20040330" and "wiring circuit board" and "bump" with "solder ball"   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/02/23 11:51 |
| S65 | 2  | ("6429096").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 09:46 |
| S66 | 2  | ("6627988").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 09:48 |
| S67 | 10 | ("20010009302"   "5229643"   "5554887"   "5903052"   "5920117"   "6184580"   "6219243"   "6259156").PN. OR ("6627988").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2006/09/11 09:47 |
| S68 | 2  | ("6376769").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 09:58 |
| S69 | 91 | ("3555364"   "4734825"   "5043794"   "5148265"   "5172303"   "5192716"   "5286926"   "5347159"   "5367764"   "5371654"   "5375041"   "5386341"   "5394303"   "5473119"   "5483421"   "5548091"   "5558928"   "5570504"   "5583321"   "5665473"   "5672548"   "5682061"   "5685885"   "5686699"   "5734555"   "5777379"   "5783870"   "5794330"   "5798564"   "5801439"   "5848467"   "5861666"   "5875545"   "5901041"   "5915170"   "5926369"   "5929517"   "5943213"   "5950304"   "6108210").PN. OR ("6376769").URPN. | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2006/09/11 09:51 |

## EAST Search History

|     |    |  |   |    |     |                  |
|-----|----|--|---|----|-----|------------------|
| S70 | 2  | ("6673651").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 09:59 |
| S71 | 15 | ("5239198"   "5668405"   "5866949"<br>  "5880590"   "5895965"   "5925934"<br>  "6031292"   "6083776"   "6166443"<br>  "6201302"   "6229215"   "6259154"<br>  "6326696"   "6404049").PN. OR<br>("6673651").URPN.  | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2006/09/11 10:03 |
| S72 | 2  | ("6673651").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 10:03 |
| S73 | 2  | "20020070458"  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/09/11 10:03 |
| S74 | 75 | ("4413308"   "4581680"   "4641222"<br>  "4707657"   "5077598"   "5137461"<br>  "5148266"   "5258330"   "5352926"<br>  "5367435"   "5369551"   "5414298"<br>  "5435732"   "5450290"   "5451720"<br>  "5453580"   "5473120"   "5477082"<br>  "5477933"   "5483421"   "5491303"<br>  "5509815"   "5586010"   "5598033"<br>  "5690270"   "5700549"   "5738531"<br>  "5800184"   "5829988"<br>  "5880890").PN. OR ("6050832").<br>URPN. | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2006/09/11 10:33 |
| S76 | 55 | @ad<="20040330" and "flexible"<br>with interposer with solder with ball  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/09/11 10:42 |
| S77 | 48 | @ad<="20040330" and "flexible"<br>with interposer with "solder ball"   | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/09/11 11:03 |
| S78 | 25 | @ad<="20040330" and "flexible<br>interposer" same "solder ball"  | US-PGPUB;<br>USPAT;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB           | OR | ON  | 2006/09/11 11:49 |
| S79 | 2  | ("6830463").PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 11:49 |

## EAST Search History

|     |     |   |   |    |     |                  |
|-----|-----|---|---|----|-----|------------------|
| S80 | 2   | ("6280640").PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 12:57 |
| S81 | 2   | ("6262478").PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 12:57 |
| S82 | 2   | ("6262376").PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2006/09/11 12:57 |
| S83 | 2   | ("6830463").PN.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2007/04/11 15:07 |
| S84 | 112 | ("3555364"   "4734825"   "5043794"<br>  "5148265"   "5172303"   "5192716"<br>  "5286926"   "5347159"   "5367764"<br>  "5371654"   "5375041"   "5386341"<br>  "5394303"   "5473119"   "5483421"<br>  "5548091"   "5558928"   "5570504"<br>  "5583321"   "5665473"   "5672548"<br>  "5682061"   "5685885"   "5686699"<br>  "5734555"   "5777379"   "5783870"<br>  "5794330"   "5798564"   "5801439"<br>  "5848467"   "5861666"   "5875545"<br>  "5901041"   "5915170"   "5926369"<br>  "5929517"   "5943213"   "5950304"<br>  "6108210").PN. OR ("6376769").<br>URPN. | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | ON  | 2007/04/11 15:09 |